



Safety Notice

Appliance: Frost Free Fridge Freezer

Issue: Possibility of the defrost timer (located at the back of the fridge) to fail, overheat and cause potential fire.

Contact Beko on 0800 917 2018 (1800 25 29 25 in Eire)

Resolve: Free of charge modification to the defrost timer. Modification takes about 30 minutes to complete.

Affected Models:

Beko frost free fridge freezer models affected were manufactured between January 2000 and October 2006. These have a serial number that begins with either 00,01,02,03,04,05 or 06.

Affected Model Numbers:

CDA 539 FS/FW/FX
CDA 543 FS/FW/FX
CDA 645 FW
CDA 647 FS/FW
CDA 648 FS/FW
CDA 653 FS/FW/FX
CDA 659 FS
CDA 751 FS/FX
CDA 752 FS/FW/FX
CS 460 FF/FFS/FFW/FFSD
CS 461 FFW/FFS
CSA 4706 FFX
CSB 4606 FFSD/FFS/FFW
CA 5411 FFS/FFW/FFX
CA 7014 FFX
CA 7015 FFW/FFS/FFX

Safety Checker:

<https://refsafety.beko.co.uk/Home/Intro>