



## Safety Notice

Appliance: 6kg and 7kg Condenser Tumble Dryer

Issue: Possibility of a component failure which can overheat, leading to a potential risk of fire.


Resolve: Free of charge modification in the home. **If the appliance is one of the affected appliances stop using it immediately and disconnect it from the wall socket as a precaution.**

Affected Models:

Beko 6kg & 7kg Condenser Tumble Dryers purchased May and October 2012 to carry out a free of charge modification. The first 2 digits of the serial number give year of production and the last 2 digits give the month of production.

Affected Model Numbers:

Model Numbers	Serial Numbers
DCU6130W	
DCU6130S	
DCU6130B	
DSC64W	12-xxxxxx-05
DSC64S	12-xxxxxx-06
DC7110W	12-xxxxxx-07
DC7041W	12-xxxxxx-08
DCU7230W	12-xxxxxx-09
DCU7230S	12-xxxxxx-10
DCU7230B	



Safety Checker:

<https://dryersafety.beko.co.uk/Home/Intro>

Contact:

Call Beko free of charge on 0800 9172018 or 1800 25 29 25 in Eire. Opening hours are 08:00 and 20:00 Monday to Friday. 10:00 to 16:00 on Saturday and Sunday